

Attachment 6: Table of Control Measures

1. Accelerated Implementation

- a. Accelerated shutdown and replacement of Clairton Coke Works Batteries 1-3
- b. Implementation of Contingency Measures as RACM/RACT
 - i. Battery B wall rebuilds, door leaks, and PEC baghouse
 - ii. Battery 19 wall rebuilds, door leaks, and traveling hot car (assuming excess emissions were included in baseline)
 - iii. Battery 20 wall rebuilds, door leaks, and traveling hot car (assuming excess emissions were included in baseline)
 - iv. Ultra low sulfur diesel fuel

2. Additional Control Measures

- a. Replacement of quench tower #5, #7, and/or B
- b. Establishment of lower limits for maximum quench water TDS concentrations and/or requiring quench water pretreatment.
- c. VOC controls